

KNOWN CORRECTIONS STILL NEEDED:

- 1. UPDATE ROTISSERIE UNIT TO LATEST VERSION.
- 2. REMOVE INFARED BURNER LEADS FROM TOP VIEW
- CORRECT DEPICTION OF GRILL IN RIGHT SIDE VIEW.
- CORRECT POSITION OF GRILL HANDLE (SHOULD BE CENTERED ON LID FACE)